

INVOICE

RPP Service Company LLC
2202 E US Highway 80
White Oak, TX 75693-2336

Michael@rppsvc.com
+1 (903) 236-5030



Bishop Lifting - Matex:Morton Salt Mine:15137 08

Bill to
Bishop Lifting
Morton Salt Mine
1975 FM 1252 East
Kilgore, TX 75662

Invoice details

Invoice no.: 15137
Terms: Net 15
Invoice date: 02/18/2026
Due date: 03/05/2026

P.O. Number: PO 000135900
VIN#: 0300127622
Unit ID: 08

#	Product or service	Description	Qty	Rate	Amount
DOS: 02/16/2026 - Service Call to Morton Salt Mine, Grand Saline, TX 75140.					
Customer Reports: Alternator plug not making good contact for Unit 08, SN: 0300127622, JLG 600S Telescopic Boom Lift.					
While still down in the mine, located unit 08. Setup and swung motor away from unit. Removed the bad plug and bad section of the wiring. Installed new plug. Tested and the unit is still having voltage issues. Recommended to customer that a new harness is needed. Released unit back to customer.					
1.	SS-Fee	Consumables used in the process of repairs	1	\$37.50	\$37.50
2.	S2533	Electrical Connector	1	\$18.99	\$18.99
3.	S/C-Fee	Service Call/Mileage Fee (Included on Inv 15136 Unit 12)	1	\$0.00	\$0.00
4.	S/C-Labor	Service Call Labor: Seth	4.5	\$150.00	\$675.00

We appreciate you and your continued business!

Ways to pay

BANK

Note to customer

Total

\$731.49

RPP Service Company assumes no liability nor offers any warranty for any customer supplied parts. RPP Service Company reserves the right to increase the quoted price, if the cost of materials necessary for repair services increases prior to the repair service date. RPP Service Company shall have no liability for any losses/damages resulting from any defective products sold pursuant to this invoice, including without limitation to any cargo loss, loss of use or any incidental or consequential damage resulting from any such defective products. CHECK NUT TORQUE SPEC BETWEEN 50-100 MILES OF OPERATION AFTER WHEEL SERVICE AS RECOMMENDED BY ATA-TMC, NWRA, AND TRUCK OE MANUFACTURERS.

[View and pay](#)